

ENTRIES	TIME
OHARE RM 3C. LAST ENTRY AT	0345
SILENT PERIOD	48
NRUI V NPM ZNU ZNW NR 2 / R C NR 1 NR 2 MAKE THAT NR 2 / NR/ ZAG VA	50
NO SIGS	53
NMC V NRUI ZOY O ZOZ AR/ ZOYO / HAVE U ESTABLISHED CONTACT WITH PLANE YET	58
HRD HER BUT DNT KNW IF SHE HRS US YET / ZPH 3105/ ZPK 3105/ ZAG	0400-03
GAVE WX TO EARTHART ON FONE 3105	07
ALSO ON KEY	10-
NO SIGS	13
TUNED TO EARTHART ON 3105 KCS	15-20
EARTHART UNHRD ON 3105 KCS THIS TIME	23
NO SIGS	26
GIVING EARTHART WX ON KEY 3105	35
GIVING WX TO EARTHART ON FONE 3105	40
NMC V NRUI ZOY O ZOZ / ZOY O/ ZAG VA/ NPM V NRUI ZOY O ZOZ AR/ ZOY O	40-50
NPM V NRUI U HR EARTHART ON 3105 / YES BUT CANT MAKE HER OUT/	55
TUNED TO EARTHART / NO HR	56
WORKING NPM NA/ EARTHART BROKE IN ON FONE 3105 / NW ??? UNREADABLE	57
TOLD NPM AS AS	0500
SENDING WX TO EARTHART ON KEY 3105	03
WX ON FONE N	08
NO SIGS	10
NPM V NRUI ZPH 3105 FONE / NRUI V NPM ZZA CZW AR/ R BT NMC V NRUI	13-20
ZOY O ZOZ AR/ NRUI V NMC ZOY O AR/ NMC V NRUI R ZAG VA	23
NMC V NRUI ZPH 3105 AR/ NRUI V NMC 3105 ZPK AR/ R ZAG VA	26
TUNED TO 3105 FER EARTHART SIGS / UNHRD/	30
NO SIGS	33
SENDING WX ON KEY TO EARTHART	36
SAME ON FONE	39-42
SAME ON KEY AGN	45-50
UNHRD	51
OBSERVING SKED ON 7500 KCS A'S	54
TUNING FER EARTHART ON 3105	0600
NRUI V NPM ZFU AR/ SHIFTING FREQS	01
NO SIGS	05
NRUI V NMC P BT ZWB ZWB AR/ GAVE IT TO IM/ NRUI V NMC R R	06
SENDING WX TO EARTHART ON KEY	07
SAME ON FONE	10
OFF AT	12
TUNING FER HER	13
NPM V NRUI ZOY O ZOZ / UNHRD/ ZAF ZAG VA	20-23
EARTHART ON 3105 NW / WANTS BEARING 3105 ETC	30
800 MILES OUT	33
WORKED HMLAND AND PASSED ONT HE DOPE TLD IM TAKE BEARINGS ON 3105 ETC	34
NPU NPU NRUI V NPM NPM VVVV ZFU	36
SENDING A'S ON 7500 KCS/ CANT ANS NPM YET	39
NPU V NPM VVVV'S	42-4
CALLING EARTHART ON 3105	47
NO SIGS	50
EARTHART ON NW RECEPTION FAIRLY CLR NW	56
WANT BEARING ES INTS REPT IN 1/2 HR	
CALLING HMLAND	
GAVE HIM THE DOPE FER RELAY TO MR BAKER / ETC	