

RADIO LOG

ITASCA

Date 2 JULY 1953

W L GALTEN, RM 3C.-ON

ENTRIES

TIME

STILL BUSI KHAQQ SKD-NIL	0001-10
NPM V NRUI ZFU AR/ NRUI V NPM ZOY O ZAD NIJP 8470 ZAB NPU AR/ NPM	
V NRUI R BK NPU V NRUI ZAD NPM BK NIJP V NRUI ZFU 8470 AR / UNANSWD	13-19
NPM V NRUI INT NIJP ZOY Z NRUI AR / NRUI V N C R AS / R	20
NPM V NRUI ZAF XX ZAG VA / NRUI V NPM R	23
TH BUSI 7500 WID KHAQQ WX XMITTING -A-A-S / UNANSWD ON 3105	25-35
NPM V NRUI ZOZ AR/ NRUI V NPM R ZOY O ANI DPEON EARTHART ? / NPM,	
R ZZA BK ZCX KHAQQ AR / NRUI V NPM R / NPU V NRUI ZOZ AR/ UNANSWD	36-8
NMC V NRUI ZOZ AR / NRUI V NMC ZOY O AR / NMC V NRUI R ZOY O BK NPU	
V NRUI ZOZ AR/ UNANSWD	40-4
LSNIN 3105 FER KHAQQ- PER TH/ NIL	45-50
NO SIGS	53
LSNIN 7500 FER KHAQQ HRD ER / ES TH/ NIL	95-9
TH XMITTING A-S HMLND ON 7500 / ALSO SENT A 3 ON 3105 REQUESTING A	
KEY BE SUED IN OBSERVING SKDS AS NIL FM KHAQQ / UNANSWD	0100-7
NMC V NRUI P AR/ NRUI V NMC K	10
NRUI V NMC R NR 1 : 23 6002/0112 K	16
NRUI V NMC R NR 2 : 24 6002/0113 ZOY O / R ZOY ZAG VA	18
LSINING 7500 / 3015 FER KHAQQ / NIL - XMITTING	2025
DITTO - ONLY ER L8IN 3105 - NIL	25-29
KHAQQ DE NRUI A-S / ALSO KHAQQ FM ITASCA HAVE NOT HRD UR SIGS YET	
PLS OLSVR SKDS WID KEY GA AM LSNIN 3105 NW / UNANSWD	30-9
NPM V NRUI ZOY 1 ZFU AR/ NRUI V NPM V-S BK INT K / NRUI V NPM P	
INT K / K	40
NPM V NRUI R NR 1: 25 1002/0100 K	41
NPM V NRUI R NR 2: 26 SVC B/ K	43
NRUI V NPM R NR 1: 24 6002/ 0113 ZAG ZAF VA	45
LSNIN FER KHAQQ / NIL UNHRD	45-50
NO SIGS	53
KHAQQ DE NRUI XMITTING WX ETC.	55-8
RELD BY T.J. O'HARE RM 3C	
	CLR EXCEPT FER KHAQQ SKDS/ WL GALT
	WL GALTEN59
SENDING A'S ON 7500 / AS PER SKED	0200
NPU ON 500 NIL	03
NO SIGS	06
NPM NPM V NRUI ZOY O ZOZ AR/ NRUI V NPM ZOY O PSE NRJ ZPJ NRUI NR 1 TO	
NMC WANT FER OU FILES /RR/ SENT NR 1 AS REQUESTED /	
NRUI V NPM RR TU/ LISTENED TO 3105 AT 15 TO 18 /	25
SENDING A'S ON 7500 KCS AS PER SKED	30-
ABLE HEAR EARTHART AT(ON 3105)	45
SENT NMC ES NPM P NR 3 TO BOTH SRS 27 / R FM BOTH AT	56
OBSRVD SKED WITH EARTHART AND GAVE WX ON FONE AT	0305
NO SIGS	08
NPM VES NMC B NR 3 FM NRUI AR/ NMC V NPM RR / R ZAG NIL	12
TUNED TO 3105 FER EARTHART	14
EARTHART UNHRD	2 1
OBSERVING SKED WITH EARTHART ON 7500 AS PER SKED	28
SENT WX ON 3105 ON FONE AS PER SKED	35
SENT PRESS TO NMC NR 4 SRS 28/ NRUI V NMC R	40
HRD EARTHART PLANE ON 3105	45

ENTRIES	TIME
OHARE RM 3C. LAST ENTRY AT	0345
SILENT PERIOD	48
NRUI V NPM ZNU ZNW NR 2 / R C NR 1 NR 2 MAKE THAT NR 2 / NR/ ZAG VA	50
NO SIGS	53
NMC V NRUI ZOY O ZOZ AR/ ZOYO / HAVE U ESTABLISHED CONTACT WITH PLANE YET	58
HRD HER BUT DNT KNW IF SHE HRS US YET / ZPH 3105/ ZPK 3105/ ZAG	0400-03
GAVE WX TO EARTHART ON FONE 3105	07
ALSO ON KEY	10-
NO SIGS	13
TUNED TO EARTHART ON 3105 KCS	15-20
EARTHART UNHRD ON 3105 KCS THIS TIME	23
NO SIGS	26
GIVING EARTHART WX ON KEY 3105	35
GIVING WX TO EARTHART ON FONE 3105	40
NMC V NRUI ZOY O ZOZ / ZOY O/ ZAG VA/ NPM V NRUI ZOY O ZOZ AR/ ZOY O	40
NPM V NRUI U HR EARTHART ON 3105 / YES BUT CANT MAKE HER OUT/	40-50
TUNED TO EARTHART / NO HR	55
WORKING NPM NA/ EARTHART BROKE IN ON FONE 3105 / NW ??? UNREADABLE	56
TOLD NPM AS AS	57
SENDING WX TO EARTHART ON KEY 3105	0500
WX ON FONE N	03
NO SIGS	08
NPM V NRUI ZPH 3105 FONE / NRUI V NPM ZZA CZW AR/ R BT NMC V NRUI	10
ZOY O ZOZ AR/ NRUI V NMC ZOY O AR/ NMC V NRUI R ZAG VA	13-20
NMC V NRUI ZPH 3105 AR/ NRUI V NMC 3105 ZPK AR/ R ZAG VA	23
TUNED TO 3105 FER EARTHART SIGS / UNHRD/	26
NO SIGS	30
SENDING WX ON KEY TO EARTHART	33
SAME ON FONE	36
SAME ON KEY AGN	39-42
UNHRD	45-50
OBSERVING SKED ON 7500 KCS A'S	51
TUNING FER EARTHART ON 3105	54
NRUI V NPM ZFU AR/ SHIFTING FREQS	0600
NO SIGS	01
NRUI V NMC P BT ZWB ZWB AR/ GAVE IT TO IM/ NRUI V NMC R R	05
SENDING WX TO EARTHART ON KEY	06
SAME ON FONE	07
OFF AT	10
TUNING FER HER	12
NPM V NRUI ZOY O ZOZ / UNHRD/ ZAF ZAG VA	13
EARTHART ON 3105 NW / WANTS BEARING 3105 ETC	20-23
800 MILES OUT	30
WORKED HMLAND AND PASSED ONT HE DOPE TLD IM TAKE BEARINGS ON 3105 ETC	33
NPU NPU NRUI V NPM NPM VVVV ZFU	34
SENDING A'S ON 7500 KCS/ CANT ANS NPM YET	36
NPU V NPM VVVV'S	39
CALLING EARTHART ON 3105	42-4
NO SIGS	47
EARTHART ON NW RECEPTION FAIRLY CLR NW	50
WANT BEARING ES INTS REPT IN 1/2/ HR	56
CALLING HMLAND	
GAVE HIM THE DOPE FER RELAY TO MR BAKER / ETC	

RADIO LOG ITASCA

Date 2 JULY, 193

ENTRIES	TIME
O'HARE RM 3 C. LAST ENTRY AT C.R.M. STANDING BY AT ALL TIMES	0658
WORKING HOWLAND I ON KEY ES FONE	0700-03
SENDING A'S ON 7500 KCS AS PER SCHED	08
SHIFTED TO 3105 NW	08
NW ON 7500	12
BACK TO 3105 A'S ETC	14
CALLING EARTHART ON 8105 FONE NW / NO ANS / SENDING A'S ON 3105 NW	15 -17
ON FNE NW / CUM IN PSE	23
TOD HER CA ON 3105	27
CALLING CONSTANTLY ON 3105 ON FSE ES KEY / THOMPSON RM3C ON D/F	30
EARTHART ON NW SEZ RUNNING OUT OF GAS ONLY 1/2 HR LEFT CANT HR US	
AT ALL / WE HR HER AND ARE SENDING ON 3105 ES 500 SAME TIME CONSTANTLY	40
AND LISTENING IN FER HER FREQUENTLY	50
STILL SENDING ON 3105 VOICE AND KEY A'S ON KEY	55
SENDING CONSTANTLY ON 7.5 MEGS AND 3105 CALLING HER AND TELLING HER	0800
TO CA ON 3105 THAT WE HEAR HER / STOPPING FREQUENTLY TO LISTEN IN FOR	
HER / LOG AT PSN NR 2 KEEPING PERTINENT DATA	56
ON 7500 AGN / AMELIA ON AGN AT 0800 SEZ HRS US ON 7.5 MEGS CA/	57
STILL SENDING ON 7500 KCS TELLING HER TO CA ON 3105 AND SENDING OUT SIGS FER	
HER TO OBSERVE BEARINGS ON / MAINTAINING LISTENING WATCH 3105 ES 7500	0908
ES 500	09
STOP SENDING TO TUNE IN SIGNALS IF ANY ON 7500 ES 3105	12
NOTHING HRD AS YET	
SENDING ON 7500 KCS TELLING HER TO ANS ON 500 OR 3105	15
REPEATING ABOVE CONSTANTLY AND LISTENING ON THOSE FREQS	25
TUNING ON 6210 KCS / PSN 2 ON 3105 KCS / D/F ON 500 KCS N N N	35
CALL DE HOWLAND I ES TOLD IM GET D/F CG AT ALL COST VA/ 7500	
CALLED EARTHART ON 7500 KCS ES TOLD HER ANS ON 3105 AM TUNING NW FER HER	36
TUNING BROADLY ON 7500 / NR2 TUNING ON 3105 KCS NR3 D/F	
ON BRIDGE ON 500 KCS UNABLE READ HER/	38
STILL TUNING FER HER NOTHING HRD YET	42
KHAQQ DE NRUI / SEVERAL TIMES . WE CAN HEAR U GOOD ON 3105 SO PSE	GVE US
YOUR PSN ES CA ON 3105 AR KKK THIS WAS SPELLED OUT IN FULL	45/48
STILL TUNING HR ON 7500 KCS NOTHING AS YET	51
SAME	54
SAME	57
SAME	1000
NRUI V NRUI GET D/F CG AT ANI COST/ RPTD/ BT CALLED EARTHART ON	
7500 KCS AND SEZ WE HEARD U ON 3105 KEEP ON USING 3105 GO ON 3105	AR/05
NPM NPU V NRUI AR/ NRUI V NPMK/ NMF V NRUI	
SENT NPM NR 3 ES 4 SRS 30 31 / R V NPM AT / 1020 1023	08
RECVD PRIORITY NR 3 SRS 32/ R'D AT	28
BACK ON 6201 KCS MAINTAINING LISTENING WATCH FER PLANE	30
RELEIVED BY GALTEN RM 3C. SITUATION SAME - O'HARE RM 3C.	33
WRD FM D/F/ MAN TT WGEN WAS CALLING NRUI ON 500	34
WGEN DE NRUI QRU? QSY 600 ARK / UNASRD	35-42
NRUI DE WGEN / WGEN DE NRUI K/ NRUI DE WGEN HAS EARTHART XXXXXX NOW-	
LAND YET? / WGEN DE NRUI NOT YET/ R TU	43-44
LSNIN 6210 FER KHAQQ / NIL BG	45-50
SAME	53
KHAQQ DE NRUI A-S WE HEAR YOUR SIGS OK ON 3105 2 HOURS AGO GO AHEAD	
ON 3105 OR 500 KCS 7500 / UNANSVD	



ENTRIES	TIME
REPEATED WX ON FONE//	0300
NOTHING HEARD FROM EARHART//	- 15, 18
SENT WX AT	30
A A A A A DE NRUI / HOWLAND	34/
REPEAT WEATHER ON FONE 3105//	35
EARHART HEARD FONE/ WILL LISSEN ON HOUR AND HALF ON 3105-SEZ SHE	45/4--
BROADCAST WEATHER FONE 3105//	0400
REPEATED WEA ON KEY/ 3105 KCS/	02
EARHART UNHEARD//	15/18
BRDST WX ON KEY AND FONE//	30/35
SENT WEATHER /CODE/FONE/ 3105 KCS--(HEARD EARHART -(PART-GLDY)----	53
-----	0500
EARHART UNHEARD//	15/18
SENT WX AT- FONE KEY- 3105	30/35
AAAAAAAAAANRUI TO 7500 KCS//	40
NO HEAR DURING ((SETTING ON 3105 ALL TIMES//	45/50
SENT WEATHER / CODE AND KEY 3105 KCS/	0600-05
WANTS BEARING ON 3105 KCS// ON HOUR// WILL WHISTLE IN MIC	14//
ABOUT TWO HUNDRED MILES OUT// APPX// WHISTLING// NW	15
AAAAAAAAANRUI (7500)-(LISTENING THRU ON 3105 )	30-
AAAA NRUI --	35
CALLED EARHART ON 3105 VOICE//	36
AAAAAAAA NRUI NRUI TO //PSE ACKN 3105	41
PSE TAKE BEARING ON US AND REPORT IN HALF HOUR--	45
I WILL MAKE MOISE IN MIC -ABT 100 MILES OUT	46
AAAAAAAAAAAA 7500	0705/
AAAAAAAA - 3105	08/12
AAAA NRUI ETC// 7500	12-14
AAAAAA NRUI 2800 3105	14-16
FONE TO EARHART/ CANNOT TAKE BEARING ON 3105 VY GOOD/ PLESE SEND ON	
500 OR DU WISH TAKE BEARING ON US / GA, PSE// NO ANSWER	18
KHAQQ DE NRUI A-S GA 3105 / UNANSWD <i>Disseminated off to 9th.</i>	19-24
KHAQQ FM ITASCA PLS GA ON 3105 KCS / UNANSWD / CRM/DC NOW ON THE	25
KHAQQ DE NRUI A-S GA 3105 / UNANSWD / NRUI'S MAIN D/F 500 KCS	26-9
KHAQQ FM ITASCA PLS Y OUR SIGS ON KEY PLS / UNANSWD	30
KHAQQ DE NRUI A-S	31-4
KHAQQ DE NRUI A-S, 7500 KCS	35-40
KHAQQ DE NRUI A-S, 3105 KCS	41
KHAQQ CLNG ITASCA WE MUST ON YOU BUT CANNOT SEE U BUT GAS IS	
RUNNING LOW BEEN UNABLE TO REACH YOU BY RADIO WE ARE FLYING AT A	
1000 FEET	42
KHAQQ DE NRUI R MSG R QSA 5 R A-S (500 ES 3105) GA / UNANSWD	43-6
KHAQQ DE NRUI R MSG R QSA5 R A-S (3105)	47-8
KHAQQ FM ITASCA UR MSG OK PLS Y WID A3, A3/3105 / A-S FM NRUI A2	49-50-57
KHAQQ CLNG ITASCA WE ARE CIRCILING: BUT CANNOT HR U GA ON 7500 WID A	
LNG COUNT EITHER NW OR ON THE SKD TIME ON 1/2 HOUR (KHAQQ S5 A3)	58
KHAQQ DE NRUI A-S, 7500 / GA 3105	
KHAQQ CLNG ITASCA WE RECD UR SIGS BUT UNABLE TO GET A MINIMUM PSE	
TAKE BEARING ON US AND ANS 3105 WID VOICE / NRUI DE KHAQQ LNG DASHES	
ON 3105 / NRUI2 DE NRUI P AR	0800-3
NRUI2 GIVING TO DPE TT NO SIGS ON 3105 ES IMPOSSIBLE TO WRK ITA / R	04
KHAQQ FM ITASCA UR SIGS RECD OK WE ARE UNABLE TO HEAR U TO TAKE A	
BEARING IT IMPRACTICAL TO TAKE A BEARING ON 3105 UR VOICE HW DO U	
GET TT GA / UNANWD, 3105	05
KHAQQ DE NRUI GA ON 3105 OR 500 K. 7500	06

RADIO LOG \_\_\_\_\_ ITASCA \_\_\_\_\_ Date \_\_\_\_\_ 2 JULY, 1937

ENTRIES	TIME
W L GALTEN, RM3C ON - CGR-32-1	
KHAQQ DE NRUI GA 500 WID DASHES ON 500 K / UNANSWD	0805-8
KHAQQ FM ITASCA DID U GET TT XMISION ON 7.5 MEGS GA ON 500 KCS SO TT WE MAY BE ABLE TO TAKE A BEARING ON U IMPOSSIBLE TO TAKE A BEARING ON 3105 - PLS ACKNWL DGE THIS XMISION WID A3 ON 3105 GA / UNANSWD	11
KHAQQ DE NRUI RPTING ABVE INFO ON 7500 / NO ANSWR	12-14
KHAQQ FM ITASCA DO U HR MY SIGS ON 7500 KCS OR 3105 KCS PLS ACKNWL DGE WID RECEIPT ON 3105 KCS WID A3 GA / UNANSWD	15
KHAQQ DE NRUI REPTED ABVE DPE ON 7500 GA 3105 A3 AR / UNANSWD	16-7
KHAQQ FM ITASCA WL U PLS Y OUR SIGS ON 7500 OR 3105 GA WID 3105 A3	18
KHAQQ UNANSWD	19
KHAQQ DE NRUI GA 3105 A3 KCS WID REPORT OUR SIGS	20-3
KHAQQ DE NRUI GA 3105 KCS WID A3 ES XMIT POSN REPT ES QSA ON OUR SIGS	24-6
ITASCA TO EARHART WE XMITING CONSTANTLY ON 7.5 MEGS DO U HR US KINDLY CFM RECEIPT ON 3105 WE ARE STANDING BY, A3/3105	27
KHAQQ DE NRUI ANS 3105 A3 K / UNANSWD	28X-9
KHAQQ DE NRUI ANS 3105 KCS WITH REPORT ES POSN, <del>XX</del> 7500 / UNANSWD	30-1
EARHART FM ITASCA WL U PLS CUM IN AND ANS ON 3105 WE ARE XMITING CONS-TANTLY ON 7500 KCS WE DO NOT HR U ON 3105 PLS ANO 3105 GA / UNANSWD	33
KHAQQ DE NRUI ANS 3105 KCS WID A3 HW OUR SIG QSA? GA / UNANSWD	34-41
LSNIN 3105 / NIL - CRM TUNIN UP T16 FER XMISION TO NMC	XX 42
NMC V NRUI P AR, 12600 / UNANSWD	XX-43
KHAQQ TO ITASCA WE ARE ON THE LINE 157 337 <del>WE</del> WL REPT MSG WE WL REPT N ES S THIS ON 6210 KCS WAIT, 3105/A3 S5 (?/KHAQQ XMISION WE ARE RUNNING ON <del>XX</del> LINE	44-6
LSNIN 6210 KCS / KHAQQ DE NRUI HRD U OK ON 3105 KCS <del>XX</del> , 7500	44-6
KHAQQ DE NRUI PLS STAY ON 3105 KCS DO NOT HR U ON 6210 MAINTAIN QSD ON 3105, 7500 / UNANSWD	47
NIL ON 3105 OR <del>XX</del> 6210 FM KHAQQ / KHAQQ DE NRUI ANS 3105 KCS	48
KHAQQ DE NRUI ANS 3105 KCS A3 / UNANSWD	49-53
KHAQQ DE NRUI UR SIGS OK ON 3105 GO AHEAD WITH POSN ON 3105 OR 500 KCS / UNANSWD	54-0907
LSNIN 3105 AND 6210/500 KCS / NIL	08
KHAQQ DE NRUI ANS 3105 OR 500 UR SIGS OK ON 3105 GA WID POSN, 7500	09-13
LSNIN 6210 ES 3105 - NIL / 500 NIL	14
LSNIN 3105, 6210, 500 AND 500 D/F - NIL	15-33
NRUI2 V NRUI - PER TO, REF HI FREQUENCY D/F, 7500	34
KHAQQ DE NRUI GA ON 3105 KCS, 7500 / UNANSWD	35
NIL FROM KHAQQ / 3105, 6210, 500 OR 500 D/F	36-41
KHAQQ DE NRUI: XMITING DPE ON ANSWING FREQS / WE CAN HEAR U FINE ON 3105 PLS GA ON 3105, 7500 / UNANSWD	42-6
NIL FROM KHAQQ	49
NIL FROM KHAQQ / 3105, 6210, 500 OR 500 D/F	52-9
NRUI2 V NRUI: - PER TO / GET THE RDO COMPASS WRKING NOW, 7500	1002-2
KHAQQ DE NRUI WE HEARD YOU ON 3105 KCS, ETC - 8500	03-5
NPM NPU V NRUI V-S ZME / NPM V NRUI INT ZCT KHAQQ INT ZCY KHAQQ AR	08-10
NRUI V NPM ZZA INT FREQ AR / 3105 / R ZOZ AR / DID U HERE KHAQQ AT ALL AR / ZZA /R THAT T TO NPU / R (NPM/NRUI - 12600/13380) - PER TO	12
NRUI V NPM AR / NPM V NRUI RK / <del>BM</del> 3 B NR3 / R AS	14
TO ENGAGED NPM: XMITING P MSGS, 12600	15-26
DC ENGAGED NPM: RECIVING P, 12600 / LSNIN 3105 CONSTANTLY, NIL / BG	27-30
BG OFF TO DC//	35
WGEN WGEN DE NRUI NRUI QRU IMI	38
WGEN WGEN DE NRUI QRU 600 K	39