


A COLLISION
BULKHEAD
COULD HAVE
STOPPED FIRE

HOLD WAS EMPTY
NO CARGO TO BURN


TOILETS
SEE TANKS ABOVE
THESE AREAS IN
PHOTO OF N.C.

SEE PORT HOLES
IN PHOTO OF
NORWICH CITY
VENTILATION?

STAIRS



EXAMPLE OF SUGGESTED PLAN
FROM ARTICLE ON TRAMP STEAMERS



STRUCTURE
POSSIBLY
OVER STAIRWAY

POSSIBLE SEA WATER TANK
FOR FLUSHING TOILETS
SEE TYPICAL PLAN




CREW QUARTERS

S.O.S MARKED MIRRORED ON
INSIDE OF SHIP
TO BE USED AS A GUIDE
FOR PAINTING OUTSIDE S.O.S.

SEAM USED AS GUIDE HORIZONTALLY
VERTICAL DISTANCE ADJUSTED BY GRIP
ON HANDLE PRE SET BY INSIDE ALIGNMENT

SEAM IN HULL OPENED
BY COLLISION
WITH ISLAND



HOW TO PAINT S.O.S ON OUTSIDE
OF SHIP FROM AN INSIDE DECK